

General Environmental Incident Summary

Incident: 944 **Date/Time Notice:** 8/21/2007 0810 **DEM Incident No:**

Responsible Party: Bobcat Company

Date Incident: 8/21/2007 **Time Incident:** **Duration:**

County: Burleigh **Twp:** 138 **Rng:** 80 **Sec:** 3 **Qtr:**

Lat: 46.80198 **Long:** -100.76260 **Method:** Derived from TRS

Location Description: 521 South 22nd Street, Bismarck, ND

Submitted By: Melvin Fisher

Affiliation:

Address:

City:

State:

Zip:

Received By: Mike Ell

Contact Person: Dave Owens
521 South 22nd Street
Bismarck, ND 58506-5556

Distance Nearest Occupied Building: 0 Feet

Type of Incident: tank leak

Description of Released Contaminant: Bonderite 1070

Volume Spilled: 250.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

A tote containing the product was ruptured in the loading/unloading dock located on the north side of the facility.

Risk Evaluation:

of Fatalities: 0

of Injuries: 0

Affected Medium: 02 - water

Potential Environmental Impacts:

The spilled product entered a storm sewer system which discharges to a retention pond located on site. Visual and pH monitoring of the retention pond did not indicate the product entered the retention pond.

Action Taken or Planned:

The product was being vacuumed from the storm sewer system into a tank. Around 300 gallons of product and water was removed. Absorbant material was spread around the spill area to absorb product on the dock. The color and pH of the retention pond was being continually monitored to determine if any product was entering the pond. If this were to happen, then the water in the pond would be removed.

Wastes Disposal Location: The recovered waste would be disposed of in the company's water treatment system. This is how the company normally disposes of the product.

Agencies Involved: City of Bismarck